

LaMotte Test Strips

LaMotte offers a convenient, economical way to perform spot checks for several water quality factors. LaMotte test strips are a great way to monitor water without having to use reagents or field kits.













Single Factor Test Strips

Test Factor	Code	Range (ppm)	# of Tests Per Vial	Values (ppm)
Chlorine Dioxide	2999LR	0-10	50	0, 0.25, 0.5, 1, 3, 10
Chlorine Dioxide	3002	0-500	50	0, 10, 25, 50, 100, 250, 500
Chlorine, Free, Low Range	2964-G	0-10	25	0, 0.25, 0.5, 1, 3, 5, 10
Chlorine, Total, Low Range	2963LR-G	0-10	25	0, 0.25, 0.5, 1, 3, 10
Chlorine, Free, High Range*	3031	0-800	50	0, 50, 100, 250, 500, 800
Chlorine, Total	2979	0-5	50	0, 0.5, 1, 3, 5
Hardness, Low Range	2981	0-180	50	0, 30, 60, 120, 180
pH, Wide Range	2974	4-10 (pH)	50	4, 5, 6, 7, 8, 9, 10
Peracetic Acid, Low Range	3000LR	0-50	50	0, 5, 10, 20, 30, 50
Peracetic Acid	3000	0-160	50	0, 10, 20, 50, 85, 160
Peracetic Acid, High Range	3000HR	0-1,000	50	0, 50, 100, 250, 500, 1000
Hydrogen Peroxide	2984LR	0-50	25	0, 1, 3, 10, 30, 50
Hydrogen Peroxide, High Range	2984	0-90	25	0, 15, 30, 50, 90
QAC, Dual Range	2934	0-80, 0-800	50	0, 10, 20, 40, 80; 0, 100, 200, 400, 800

^{*}See also chlorine test papers below.

Multi-Factor Test Strips

Test Factor	Code	Range (ppm)	# of Tests Per Factor/Per Vial	Values (ppm)
Iron & Copper	2994	0-5 (Iron) 0-3 (Copper)	25 25	0, 0.3, 0.5, 1, 3, 5 0, 0.3, 0.6, 1, 3
Wide Range pH & Total Chlorine	2987-G	4-10 (pH) 0-50 (TCI)	25 25	4, 5, 6, 7, 8, 9, 10 0, 1, 5, 10, 20, 50
Nitrate & Nitrite	2996	0-50 (Nitrate) 0-10 (Nitrite)	50 50	0, 5, 10, 25, 50 (NO ₃ -N) 0, 0.5, 1, 5, 10 (NO ₂ -N)

Sanitizer Test Papers

The chlorine and iodine test papers are chemically treated paper strips. These are packaged with a color chart in a waterproof plastic vial. Codes 2951 and 2951HR are test strips. They are also packaged with a color chart in a waterproof plastic vial. The QAC strips are specifically formulated to read all types of QAC.

Test Factor	Code	Range (ppm)	# of Tests Per Vial	Values (ppm)
Chlorine	4250-BJ	10-200 ppm	200	10, 50, 100, 200
lodine	2948-BJ	12-100 ppm	200	12, 25, 50, 100
QAC	2951	50-400 ppm	100	50, 100, 200, 400
QAC	3072-J	0-500 ppm	100	0, 100, 200, 300, 400, 500
QAC, High Range	2951HR	200-1500 ppm	50	200, 400, 600, 1000, 1500

